HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS CAL, 49-FORO, 1-A-

HABS No. CA-38-10

Addendum to
Fort Ross, Russian Chapel
Fort Ross
Sonoma County
California

Photos CA-39-10-1 through -7 have been previously transmitted to the Library of Congress.

Photographer unknown, 1930s CA-38-10-8 SOUTHWEST VIEW

CA-38-10-9 NORTHWEST VIEW

CA-38-10-10 NORTHWEST VIEW, CLOSE UP

- CA-38-10-11 Photocopy of photograph (from Society of California Pioneers,
 San Francisco)
 Photographer unknown, 1880s
 SOUTHWEST VIEW
- CA-38-10-12 Photocopy of photograph (from National Park Service Collection, California)

 Photographer unknown, ca. 1900
 SOUTHWEST VIEW
- CA-38-10-13 Photocopy of photograph (from Society of California Pioneers,
 San Francisco)
 Photographer unknown, ca. 1907
 VIEW OF RUINS OF ROOF FROM EAST
- CA-38-10-14 Photocopy of photograph (from Society of California Pioneers, San Francisco)

 Photographer unknown, ca. 1907

 VIEW OF ROOF RUINS FROM SOUTHEAST
- CA-38-10-15. Photocopy of photograph (from Society of California Pioneers, San Francisco)
 Photographer unkown, ca. 1907
 ROOF RUINS FROM WEST
- CA-38-10-16 Photocopy of photograph (from Society of California Pioneers,
 San Francisco)
 Photographer unknown, ca. 1910
 ROOF RUINS BEFORE RESTORATION
- CA-38-10-17 Photocopy of photograph (from Society of California Pioneers,
 San Francisco)
 Photographer unknown, ca. 1920
 SOUTHWEST VIEW AFTER RESTORATION